

A380 Kevlar hose update



Susan Groom

Sr. Engineering Manager – Conveyance
Fluid & Electrical Distribution Division

Nathan Copenhaver

Engineering Manager – Hose / Tube / Fitting product lines
Fluid & Electrical Distribution Division



Powering Business Worldwide

Agenda

Issue

Background


Current status

Solution & next steps

Issue




- A380 hoses experiencing “weeping”
- “Weeping” phenomenon attributed to microvoids in Kevlar hose inner tube
- “Weeping” occurs predominantly between 250 to 900 flight cycles
- Severity & occurrence varies by application
- Kevlar hoses replaced with steel braided hose in some instances
- “Weeping” hoses are removed and replaced causing disruption in airline operations

Examples of “weeping” phenomenon




Background

- First identified on A380 landing gear in 2009 (AE717558-046)
- Source identified as through-wall Microvoids which ran from inner diameter to outer diameter of inner PTFE tube
- Surfaced as an industry-wide problem
 - Internal benchmarking
 - SAE committee investigations




Background

- As hose experiences thermal variation under pressure, microvoids grow until they are “through-wall”
- Weeping does not always occur when microvoids are through-wall but are indicators of potential weepage
- Severity depends on location, application and other factors




Background




Current status


- Development of new Kevlar hose underway
- Investigation into critical design parameters which influence microvoid initiation and propagation
- Current focus on 2 parameters
 - PTFE Formulation
 - Kevlar reinforcement layer design




Current product with high microvoid content




Future product with minimal microvoids




Current status




Baseline




New Tube A




New Tube B




New Tube C




New Tube D




**New Kevlar
Reinforcement 1**



**New Kevlar
Reinforcement 2**



**New tube & Kevlar
Reinforcement 1**



**New tube & Kevlar
Reinforcement 2**


Current status

- Manufacturing Updates


- ✓ Added data collection capability to preform press & extruder
- ✓ Studied lubrication variation in blended powder
- ✓ Room/powder temperature monitoring
- ✓ New batch oven (installed and operational)
- ✓ Additional inspection to evaluate concentricity of PTFE



Mixing



Billet preform



Billet Extrusion



Sintering

Standard AE334-style hose construction



Current status

- Currently investigating additional improvements in overall performance & maintenance
- Improved lay-line solution
- Improved abrasion resistance



Solution & next steps

- Design Down-select & Configuration Freeze – July 2016
- Design Validation Testing Complete – September 2016
- Qualification of -10 size hose – December 2016
- Qualification of other size hoses - 2017

Agenda

Issue

Background

Current status

Solution & next steps

Issue

- 2 hoses identified as having weepage in A380 aircraft cargo bay (ABS1401SAAKJH19, ABS1401SAAFFJ23)
- Hose assemblies consist of Kevlar (size -16) hose with a jump-sized, swaged titanium Rynglok fitting on each end
- To date, 7 hose assemblies have been returned to Eaton for investigation
 - 5 different hose material lots
 - Assembled between July 2006 – November 2008

ABS1401SAAFFJ23 (Eaton P/N AE710788-1)



ABS1401SAAKJH19 (Eaton P/N AE710831-1)



Current status

- Investigation into cargo bay hoses ongoing
- All hoses (except one) were removed for weepage. No failure occurred
- FAR J8378 failed due to a pre-sintered defect which occurred during pressure test after installation
- Returned hoses have exhibited varying levels of abrasion where the hose is clamped

Typical installation



Abrasion location at clamp interface

Returned Sample with Abrasion



Solution & next steps

Root cause investigation

- The hose is seeing movement during pressurization which is being constrained by the center clamp point
- As the hose moves, the surface of the hose rubs against the clamp resulting in abrasion of the outer cover

Next steps

- Airbus and Eaton working jointly on CRES wire braid replacement for Kevlar for this application
- CRES wire braid hose is more rigid and will not induce movement in the hose assembly
- CRES wire braid hose will replace 2 part numbers (ABS1401SAAKJH19, ABS1401SAAFFJ23)
- Redesign of the clamp will be required to accommodate the new CRES hose

Example of multi-directional stress cracks




Photo #7- Showing stress cracks at socket skirt




Photo #8- Enlarged view of stress cracks at End B



Abrasion location at clamp interface



Questions/Comments



Powering Business Worldwide