


A detailed photograph of the internal components of a CFM56 engine, showing a complex network of metal pipes, hoses, and electrical wiring. The engine is mounted within a green-painted aircraft fuselage structure. The lighting is bright, highlighting the metallic surfaces and the intricate layout of the engine's internal systems.

CFM56 VBV gear motor improvement status

Kurt Kachler

Product Sales Manager
FMC – Euclid (Engine Fuel)

Agenda

Issue

Background

Fleet management

Wear improvement status

Summary


Issue

- Platform: CFM56-5B engines (A320 family)
- Aircraft problem/impact
 - Aborted Take-Offs (ATOs), Air Turn-Backs (ATBs), Delays and Cancellations
- Description of problem
 - Inability to control air into the engine core compressor due to heavy wear of the entire CFM56-5B Variable Bleed Valve (VBV) system driven by Eaton's VBV gear motor
- Assembly/part number
 - 396800-12 VBV Gear Motor (CFM 301-774-709-0)
- Additional maintenance is required to insure reliable operation




Background

Increased torque requirements of CFM56-5B VBV system drives maintenance



-5B Evolution of removed components

- Component removals based on data supplied to CFM – since 2009
- Gear Motor, Stop Mechanism & Flexshafts are the most removed VBV components (~75% of total removals)



CFM address VBV subsystem issues with multi path approach

Fleet data and Statistics


- System primary functions
 - By-passes an amount of air from the primary airflow into the secondary to optimize compressors efficiency
- VBV disruptions can lead to operational events including ATBs & ATOs
 - Over the last 12 months (May. 14 – May. 15)

	5A	5B	5C
ATO	0	8	0
ATB	0	12	0


- Fleet disruptions are related to EGT shift, Compressor Vane E/W or Gear motor fuel leakage

Background-root cause

Heavy wear of bearing races leads to contact between the gear tips and gear housing.



Housing scoring that leads to seizure due to journal and shaft wear



Typical drive gear journal wear



Idler shaft wear (One heavily loaded quadrant)



Idler shaft (Opposite side not worn)




Fleet management

- Follow CFM service recommendations provided by CFM56-5B SB 75-0045 rev 1
- VBV system overhaul at 12,000 hours (includes 396800-12 gear motor)
- Eaton reliability data confirms the need for this mid-life overhaul

Weibull plot for Failure modes

- Assuming A and B are the Failure Modes



failure modes.
ing an infant mortality.
indicating a Wear out failure mode.
as together on one plot.



© 2013 Eaton Corporation. All rights reserved.

5

Results

TSI (in Hrs)	10000	15000	20000	25000	30000	35000	40000
Reliability with failure mode A	98%	98%	97%	97%	97%	96%	96%
Reliability with failure mode B	100%	99%	95%	77%	37%	5%	0%
Reliability with failure mode A & B (System)	98%	97%	93%	75%	36%	4%	0%

CM (in Cycles)	10000	15000	20000	25000	30000
Reliability with failure mode A	98%	97%	96%	96%	95%
Reliability with failure mode B	99%	88%	47%	5%	0%
Reliability with failure mode A & B (System)	97%	86%	45%	4%	0%

- This quantifies the reliability of Gear Motor
- (based on the data from one operator).



© 2013 Eaton Corporation. All rights reserved.


6

Wear improvement status

Eaton engineering developing wear improvement for gear motor

- Initial development testing of Titanium Zirconium Di-Boride (TZB) coating looked very promising
- Inconsistent coating adhesion was experienced
- Process to eliminate the base metal re-crystallized layer from super finish to improve TZB adhesion
- Continuing adhesion issue drove evaluation of alternative coatings

PVD coating missing following production acceptance test




Wear improvement status

Evaluation of wear alternatives

- Following certification failure of TZB coating alternative solutions were evaluated
- No Plasma Vapor Deposited (PVD) coatings demonstrated reliable adhesion during gear motor testing

Condition Following Production Acceptance Test (ATP)

Hyperlox AlTiN



The Hyperlox coating was removed from the gear journals during test.



The Hyperlox coating remained on the idler shaft after test. (Note that the ends of shaft are masked and not coated).



The information contained herein is proprietary and shall not be reproduced or disclosed to any third party without written permission of Eaton Corporation

12

Condition Following Production Acceptance Test (ATP)

Hi-Pulse AlTiCrN



The Hi-Pulse coating was removed from the gear journals during test.



The Hi-Pulse coating was removed from the idler shaft during test.



The information contained herein is proprietary and shall not be reproduced or disclosed to any third party without written permission of Eaton Corporation

13

Results of 26- hour high speed, High torque test on Hyperlox coated H-11

The Hyperlox coated (AlTiN) Idler shaft was tested for 26 hours at 3000 RPM in one direction, at 70±5 inch-lbs Torque at room temperature in Gearmotor EX-1352A. The part had no substrate wear but some of the coating did chip off.



The information contained herein is proprietary and shall not be reproduced or disclosed to any third party without written permission of Eaton Corporation

14

Summary

Evaluation of base material alternatives for improved wear continues

- Long lead times will drive late 2017 introduction at best

Adherence to CFM56-5B SB 73-045 R1 recommended

- Midlife overhaul of VBV gear motor at 12,000 hours highly recommended by CFM and Eaton

Contact your local Eaton account team for support

- Special pricing for VBV gear motor overhauled prior to 12,000 hours
- Spares support available



Questions/Comments



Powering Business Worldwide

www.eaton.com/aerospace